

APPENDIX 3

SHIRLEY AVENUE TREES CONSIDERED FOR REMOVAL											
No.	Species	Location	Height (m)	Diameter (cm)	Age	Health	SULE	Current footway gap (mm)	Future gap (mm)		Comment
									In 10 yrs	In 20 yrs	
1	Common lime	Outside 20	18	70	Mature	Good	>20yrs	740	690	640	Flared & fluted base encroaches over drive of no.18 by 500mm. Abundant basal epicormic growth.
2	Horse chestnut	Outside 66	20	84	Mature	Good	>20yrs	790	740	690	Clear of drive.
3	Horse chestnut	Outside 72	21	74	Mature	Good	>20yrs	680	630	580	Minor bark damage at base. Stem exudations at 1 & 2m on road side - possible. Clear of drive.
4	Common lime	Outside 74	26	77	Mature	Good	>20yrs	750	700	650	Slight basal epicormic growth. Clear of drive.
5	Common lime	Outside 76	24	76	Mature	Good	>20yrs	830	780	730	Flared & fluted base. Slight displacement of kerb. Abundant basal epicormic growth. Clear of drive.

NOTES

Diameter measured at 1.5m above ground.

SULE = Safe Useful Life Expectancy

Footway gap measured at ground level

Average footway width = 2.69m